



MidnightSUN
hot tubs • pools • leisure

Bemidji 218-759-8518

Brainerd 218-833-1000

Duluth 218-249-1288

Initial Treatment for @ Ease System

(Use these steps when spa water is drained and refilled)

- Add a 1/2 bottle of METAL CONTROL
- Add 4 Oz. of 4-1 CLARIFIER or UNIQUE
- Add the FROG JUMP START packet or cap of Dichlor
- Test water and make sure you're reading SmartChlor on the test strip DARK GREEN
- Set the Grey SmartChlor Cartridge at 2 to 4 and assemble it to the blue and place in the spa
- Wait until spa is at its set temperature
- Pull Out & Rinse Filters after 24 hours
- Check and adjust the pH to read between 7.2 and 7.8 using FROG TEST STRIP



Regular Maintenance

- Test water with FROG TEST STRIP and adjust the pH as needed, weekly
- Add 2 Oz. 4-1 CLARIFIER or UNIQUE weekly
- If foaming occurs use a SCUMBALL and/or FOAM OUT 1-2 Oz.
- When foam is present or cloudy add 2oz of Dichlor retest 3 min later.
- Pull out and rinse filters once every two weeks
- Add 1 packet of FROG MAINTAIN or 4 Oz. OXY SHOCK once a month.
- (ADD Oxy Plus or Maintain Packet every time Grey Cartridge is replaced)
- Once the floater flips over (Grey SmartChlor is facing up), replace the Grey cartridge.
- Frog Ease Blue Mineral cartridge lasts approx. 4 months. Once this occurs you need to buy a new Frog @Ease floating sanitizer kit.